



# PlayStation VR Cooling Fan Replacement

This guide will show you how to replace the cooling fan component of the PlayStation VR

Written By: Sarah Shand



## INTRODUCTION

A damaged or broken cooling fan can make your system overheat so it is important to replace it if that happens in order to prevent any further damage to the system.

---



### TOOLS:


- [iFixit Opening Tools](#) (1)
  - [Phillips #000 Screwdriver](#) (1)
  - [Tweezers](#) (1)
-

## Step 1 — Cooling Fan



- On one side of the console (the side adjacent to the fan vent), there will be two 6 mm screws. Unscrew them with a PH #000 screwdriver.

## Step 2



- Press and slide the side panel (it will have the two ports) back to reveal an additional 6 mm screw.
- Unscrew the 6mm screw with a PH #000 screwdriver.

### Step 3



- Slide the panel back into place.


### Step 4



- Using a plastic opening tool, carefully pry the panel from the main console to reveal the HDMI ports.
- ⓘ You will probably need to lift it on both sides in order for the panel to come loose.




## Step 5





- Turn the console over.
- Unscrew the two 9 mm screws with a PH #000 screwdriver.

## Step 6



- With the plastic opening tool, carefully pry the console shell panel free and lift it away.

## Step 7



- Using tweezers, carefully pull the multi colored bundled cable from its port connecting the fan to the console.
- Carefully lift the fan and its wiring from the device.
- ⓘ Be mindful of damaging the wires.
- ⚠ Take care to keep your fingers away from the fan blades.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-07-07 03:03:08 PM.